

**NOW  
AVAILABLE!**



**ANNOUNCES**

# ENGINE OIL PUMP PICKUP TUBE BRACKET GM LS 4.8L, 5.3L, 5.7L, 6.0L & 6.2L ENGINES

AVANTI	5.7 (350) OHV	2001-04	GMC	6.0 (364) OHV	1999-18
BUICK	5.3 (325) OHV	2004-09	GMC	6.2 (376) OHV	2007-14
CADILLAC	5.3 (325) OHV	2002-05	HUMMER	5.3 (325) OHV	2008-10
CADILLAC	5.7 (350) OHV	2004-05	HUMMER	6.0 (364) OHV	2003-07
CADILLAC	6.0 (364) OHV	2002-07	HUMMER	6.2 (376) OHV	2008-09
CADILLAC	6.2 (376) OHV	2007-15	ISUZU	5.3 (325) OHV	2003-06
CHEVROLET	4.8 (294) OHV	1999-17	PONTIAC	5.3 (325) OHV	2005-08
CHEVROLET	5.3 (325) OHV	1999-14	PONTIAC	5.7 (350) OHV	1998-04
CHEVROLET	5.7 (350) OHV	1997-04	PONTIAC	6.0 (364) OHV	2005-09
CHEVROLET	6.0 (364) OHV	1999-18	PONTIAC	6.2 (376) OHV	2009
CHEVROLET	6.2 (376) OHV	2008-17	SAAB	5.3 (325) OHV	2005-09
GMC	4.8 (294) OHV	1999-17	SAAB	6.0 (364) OHV	2008-09
GMC	5.3 (325) OHV	1999-17			

**Part number  
M29500**

**UPC: 729295105558**



## FEATURES

- Utilizes the unused screen mounting hole in the oil pump for additional clamping force
- Light weight aluminum construction
- No modifications required to install

- Does not fit pickup tubes with welded flange (GM part number 12608593)
- Does not fit Pickup tubes with two bolt hole flanges

**\*\* The application listings on this announcement are general listings to show coverage. Always consult catalog listings for detailed application information\*\***

MEMBER  
A.E.R.A  
P.E.R.A

**“Quality in all we do.”**

Melling Engine Parts • P.O. Box 1188 • Jackson, MI 49204  
517-787-8172 • Fax 517-787-5304 • [www.melling.com](http://www.melling.com)

MEMBER  
A.C.A  
M.E.M.A