

**NOW
AVAILABLE!**



ANNOUNCES

NEW DOUBLE ROLLER TIMING CHAIN FOR

BUICK 3.0-E (181) OHV 1982-85

BUICK 3.8 (231) OHV 1977-87

BUICK 4.1-4 (252) OHV 1980-84

.250" Seamless Double Roller Timing Chain

**Also available for these engines:
40404 3 piece timing set**



**Part number
40005**

UPC: 729295523864

**** Always consult catalog listings for detailed application information****

**MEMBER
A.E.R.A
P.E.R.A**

“Quality in all we do.”

**Melling Engine Parts • P.O. Box 1188 • Jackson, MI 49204
517-787-8172 • Fax 517-787-5304 • www.melling.com**

**MEMBER
A.A.I.A
M.E.M.A**