


**NOW  
AVAILABLE!**



**ANNOUNCES**

## **NEW CAMSHAFT FOR 4.3-X GM ENGINE**

<b>GMC/CHEV TK. 4.3-X (262) OHV 2003-04</b>	<b>S10, Sonoma</b>
<b>GMC/CHEV TK. 4.3-X (262) OHV 2003-05</b>	<b>Astro, Blazer, Express/Savana 2500, Safari</b>
<b>GMC/CHEV TK. 4.3-X (262) OHV 2003-13</b>	<b>Silverado/Classic 1500, Sierra/Classic 1500</b>
<b>GMC/CHEV TK. 4.3-X (262) OHV 2003-14</b>	<b>Express/Savana 1500</b>



Also available for this engine:

M155	Oil pump
M155HV	Oil pump
K-55	Oil pump repair kit
259S	Oil pump screen
258S	Oil pump screen
VS-2229	Valve spring
V1931	Intake valve
V1807	Exhaust valve
JB-2079	Valve lifter
MR-903	Rocker arm
McC1315	Camshaft
MPR-615	Pushrods
3-8MMSRH72S	Timing kit
3-8MMSRH72SA	Timing Kit

1 Required

**Part number  
MC1401**

**OE number**

**12568989**

**UPC: 729295141501**

**\*\* Always consult catalog listings for detailed application information\*\***

**MEMBER**  
**A.E.R.A**  
**P.E.R.A**

**“Quality in all we do.”**

Melling Engine Parts • P.O. Box 1188 • Jackson, MI 49204  
517-787-8172 • Fax 517-787-5304 • [www.melling.com](http://www.melling.com)

**MEMBER**  
**A.A.I.A**  
**M.E.M.A**