


**NOW
AVAILABLE!**



ANNOUNCES

A NEW BALANCE SHAFT CHAIN GUIDE

GM 2.0L & 2.5L DOHC ENGINES

BUICK	2.0-X	(122)	DOHC	2014-19	Envision, Regal
BUICK	2.5-A,Z	(153)	DOHC	2017-19	Envision, LaCrosse
CADILLAC	2.0-X	(122)	DOHC	2013-19	ATS, CT6, CTS
CADILLAC	2.5-A	(150)	DOHC	2013-16	ATS
CHEVROLET	2.0-X	(122)	DOHC	2013-19	Camaro, Equinox, Malibu, Traverse
CHEVROLET	2.5-A,L	(153)	DOHC	2013-19	Blazer, Colorado, Impala, Malibu
GMC	2.0-X	(122)	DOHC	2018-19	Terrain
GMC	2.5-A	(153)	DOHC	2015-19	Acadia, Canyon



Qty Required 1

Part number

BG5150

UPC: 729295316855

Now available as a component or as part
of the 3-1940S Balance Shaft Chain kit.
Includes mounting bolts

**** Always consult catalog listings for detailed application information****

Melling Engine Parts

P.O. Box 1188 • Jackson, MI 49204 • www.melling.com