

**NOW
AVAILABLE!**



NEW CAMSHAFT ACTUATOR FOR GM 2.0L, 2.2L & 2.4L ECOTEC ENGINES

BUICK	2.0-V	(122)	2011-13	Regal	Chevrolet	2.4-B,0,R,U,Z,5,1	(145)	2008-14	Malibu
BUICK	2.0-V	(122)	2013-16	Verano	GMC	2.4-C,K,W	(145)	2010-17	Terrain
BUICK	2.4-C,R	(145)	2010-16	LaCrosse	Pontiac	2.0-X	(122)	2007-09	Solstice
BUICK	2.4-C,K,R	(145)	2011-17	Regal	Pontiac	2.2-H	(134)	2009	G5
BUICK	2.4-K	(145)	2012-17	Verano	Pontiac	2.4-B,0	(145)	2006-10	G6
CHEVROLET	2.0-X	(122)	2008-10	Cobalt	Pontiac	2.4-B	(145)	2006-09	Solstice
CHEVROLET	2.0-X,M	(122)	2008-10	HHR	Saab	2.0	(122)	2011	9-5
CHEVROLET	2.2-H,5	(134)	2009-10	Cobalt	Saturn	2.0-X	(122)	2007-10	Sky
CHEVROLET	2.2-B,W	(134)	2009-11	HHR	Saturn	2.4-5,B	(145)	2007-09	Aura
CHEVROLET	2.4-K	(145)	2012-15	Captiva Sport	Saturn	2.4-B	(145)	2006-07	Ion
CHEVROLET	2.4-C,K,W	(145)	2010-17	Equinox	Saturn	2.4-B	(145)	2007-10	Sky
CHEVROLET	2.4-P,U,V	(145)	2006-11	HHR	Saturn	2.4-P,Z,1	(145)	2008-10	Vue
CHEVROLET	2.4-R	(145)	2014	Impala					



SERVICE GRADE COMPONENT

**Part number
VCTA-1009H
UPC: 729295237174**

**** Always consult catalog listings for detailed application information****

MELL-GEAR
Quality Melling Timing Parts Since 1946

Melling Engine Parts • P.O. Box 1188 • Jackson, MI 49204 • www.melling.com