


**NOW
AVAILABLE!**



ANNOUNCES

A NEW OIL PUMP CHAIN TENSIONER FOR FORD 2.0L & 2.3L DOHC ENGINES

FORD 2.0-9 (122) DOHC 2012-18 Edge	FORD 2.3-H (140) DOHC 2016-18 Focus
FORD 2.0-9 (122) DOHC 2013-19 Escape	FORD 2.3-H (140) DOHC 2015-19 Mustang
FORD 2.0-9 (122) DOHC 2012-15 Explorer	FORD 2.3-D,H (140) DOHC 2020-21 Mustang
FORD 2.0-9 (122) DOHC 2013-18 Focus	LINCOLN 2.0-9 (122) DOHC 2015-19 MKC
FORD 2.0-9 (122) DOHC 2013-20 Fusion	LINCOLN 2.0-9 (122) DOHC 2013-16 MKT
FORD 2.0-9 (122) DOHC 2014-18 Police Sedan	LINCOLN 2.0-9 (122) DOHC 2013-20 MKZ
FORD 2.0-9 (122) DOHC 2013-17 Taurus	LINCOLN 2.3-H (140) DOHC 2015-19 MKC
FORD 2.3-H (140) DOHC 2016-19 Explorer	



Qty per application: 1

Part number

BT7052

UPC: 729295317128

MELL-GEAR
Quality Melling Timing Parts Since 1946

Melling Engine Parts • P.O. Box 1188 • Jackson, MI 49204 • www.melling.com