

**NOW
AVAILABLE!**



ANNOUNCES

A NEW TENSIONER ARM FOR FORD/LINCOLN 2.0L & 2.3L DOHC ENGINES

FORD	2.0-9	(122)	DOHC	2012-18	Edge
FORD	2.0-9	(122)	DOHC	2013-19	Escape
FORD	2.0-9	(122)	DOHC	2012-15	Explorer
FORD	2.0-9	(122)	DOHC	2013-18	Focus
FORD	2.0-9	(122)	DOHC	2013-20	Fusion
FORD	2.0-9	(122)	DOHC	2014-18	Police Service
FORD	2.0-9	(122)	DOHC	2013-17	Taurus
FORD	2.3-H	(140)	DOHC	2016-19	Explorer
FORD	2.3-H	(140)	DOHC	2016-18	Focus
FORD	2.3-D,H	(140)	DOHC	2015-21	Mustang
LINCOLN	2.0-9	(122)	DOHC	2015-19	MKC
LINCOLN	2.0-9	(122)	DOHC	2013-16	MKT
LINCOLN	2.0-9	(122)	DOHC	2013-20	MKZ
LINCOLN	2.3-H-9	(140)	DOHC	2015-19	MKC

1 Required

Part number

BT7050

UPC: 729295317104



This tensioner arm is also included in the 3-1076S, 3-1076SA, 3-1076SAX & 3-1076SX timing sets

**** Always consult catalog listings for detailed application information****

MELL-GEAR

Quality Melling Timing Parts Since 1946

Melling Engine Parts • P.O. Box 1188 • Jackson, MI 49204 • www.melling.com