


**NOW
AVAILABLE!**



ANNOUNCES

A NEW INTAKE VALVE FOR GM 2.0L & 2.5L DOHC ENGINES

BUICK	2.0-X (122)	DOHC	2016-20	Envision	BUICK	2.5-A (153)	DOHC	2017-20	Envision
BUICK	2.0-X (122)	DOHC	2014-20	Regal	BUICK	2.5-Z (150)	DOHC	2018-19	LaCrosse
CADILLAC	2.0-X (122)	DOHC	2013-18	ATS	CADILLAC	2.5-A (150)	DOHC	2013-17	ATS
CADILLAC	2.0-X (122)	DOHC	2016-18	CT6	CHEVROLET	2.5-A (153)	DOHC	2019-20	Blazer
CADILLAC	2.0-X (122)	DOHC	2014-19	CTS	CHEVROLET	2.5-A (153)	DOHC	2015-20	Colorado
CHEVROLET	2.0-X (122)	DOHC	2016-20	Camaro	CHEVROLET	2.5-A,L (153)	DOHC	2014-19	Impala
CHEVROLET	2.0-X (122)	DOHC	2018-20	Equinox	CHEVROLET	2.5-A,L (153)	DOHC	2013-16	Malibu
CHEVROLET	2.0-X (122)	DOHC	2013-20	Malibu	GMC	2.5-A (153)	DOHC	2017-20	Acadia
CHEVROLET	2.0-X (122)	DOHC	2018-19	Traverse	GMC	2.5-A (153)	DOHC	2015-20	Canyon
GMC	2.0-X (122)	DOHC	2018-20	Terrain					

INTAKE VALVE /
8 required

Part number

V3441

UPC: 729295192466



**** Always consult catalog listings for detailed application information****

“Quality in all we do.”

Melling Engine Parts • P.O. Box 1188 • Jackson, MI 49204 • www.melling.com