


**NOW  
AVAILABLE!**



**ANNOUNCES**

**A NEW TIMING CHAIN TENSIONER ARM**

# **FORD / LINCOLN 3.5L DOHC ENGINES**

<b>FORD</b>	<b>3.5-T</b>	<b>(213)</b>	<b>DOHC (Turbo)</b>	<b>2018-21</b>	<b>Expedition</b>
<b>FORD</b>	<b>3.5-G,4</b>	<b>(213)</b>	<b>DOHC (Turbo)</b>	<b>2017-20</b>	<b>F150</b>
<b>LINCOLN</b>	<b>3.5-T</b>	<b>(213)</b>	<b>DOHC (Turbo)</b>	<b>2018-22</b>	<b>Navigator</b>



Qty Required: 1 (Left Hand)

**Part number**

**BT7055**

**UPC: 729295317272**

BT7055 is also available in timing kits 3-1079S and 3-1079SX



Quality Melling Timing Parts Since 1946