

NOW AVAILABLE!



NEW MDS DELETE KIT FOR GM 6.2L L92, L94 & L99 ENGINES

CADILLAC	6.2-F	(376)	2010-14	Escalade
CHEVROLET	6.2-J	(376)	2010-15	Camaro
GMC	6.2-F	(376)	2010-14	Yukon

Important MDS Delete Kit Notes

- When installing a delete cam, the Active Fuel Management lifters must be replaced using Non-Active Fuel Management lifters.
- The valve lifter guides used in Non-Active Fuel Management engines are different from those used in Active Fuel Management Engines and must be replaced when installing the Non-Active Fuel Management lifters
- The VLOM Must Be Replaced With A Non-Active Fuel Management Valley Cover.
- Pushrod length must be checked during installation to verify that the correct length pushrods are being used
- The vehicle engine control module/Power train control module must be reprogrammed to turn off the Active Fuel Management System in the operating software



Components must be used together

Component #	Description	Qty
MC1431	Camshaft	1 Camshaft
JB-2079	Valve Lifter	16 Lifters
MLG100	Lifter Guide	4 Guides
MF127	Thrust Plate	1 Thrust Plate
VCTO-1000	VVT Oil Control Valve	1 Valve

Part number

MDK500

UPC: 729295152019

**** Always consult catalog listings for detailed application information****

Melling Engine Parts

P.O. Box 1188 • Jackson, MI 49204 • www.melling.com