

**NOW
AVAILABLE!**



NEW ROCKER ARM FOR GM & SAAB ENGINES

BUICK	2.0-V,X	(122) DOHC	2011-15	OLDS	2.2-F	(122) DOHC	2002-04
BUICK	2.4-C,K,R	(145) DOHC	2010-15	OLDS	3.5-H	(214) DOHC	2000-02
BUICK	4.6-S,Y,J	(281) DOHC	2006-11	OLDS	4.0-C	(244) DOHC	2001-03
CADILLAC	2.0-X	(122) DOHC	2013-15	PONTIAC	2.0-X	(122) DOHC	2007-09
CADILLAC	2.5-A	(150) DOHC	2013-15	PONTIAC	2.2-F,H	(134) DOHC	2002-09
CADILLAC	4.4-D	(267) DOHC	2006-09	PONTIAC	2.4-B,0	(145) DOHC	2006-10
CADILLAC	4.6-A,Y,6,9	(281) DOHC	2000-11	PONTIAC	4.6-Y	(281) DOHC	2004-05
CHEV	2.0-M,P,X	(122) DOHC	2005-14	SAAB	2.0-Y	(122) DOHC	2003-11
CHEV	2.2-B,D,F,H,5,6	(134) DOHC	2002-11	SATURN	1.9-7	(116) DOHC	2000-02
CHEV	2.4	(145) DOHC	2006-15	SATURN	2.0-P,X	(122) DOHC	2004-10
CHEV	2.5-A,L	(153) DOHC	2013-14	SATURN	2.2-D,F	(134) DOHC	2001-07
CHEV/GMC	2.4-C,K,W	(145) DOHC	2010-14	SATURN	2.4-P,B,Z,5	(145) DOHC	2006-10

Max qty required per application: 32

**Part number
MR-1340**

UPC: 729295216667



**** Always consult catalog listings for detailed application information****

MEMBER
A.E.R.A
P.E.R.A

“Quality in all we do.”

Melling Engine Parts • P.O. Box 1188 • Jackson, MI 49204
517-787-8172 • Fax 517-787-5304 • www.melling.com

MEMBER
A.C.A
M.E.M.A