


**NOW
AVAILABLE!**



MELLING
ENGINE PARTS™
ANNOUNCES

NEW OIL PUMP CHAIN

MINI COOPER 1.6L ENGINES

COOPER	1.6 (1598) DOHC (T/C & non T/C)	2007-15
COOPER COUNTRYMAN	1.6 (1598) DOHC (T/C & non T/C)	2011-16
COOPER PACEMAN	1.6 (1598) DOHC (T/C & non T/C)	2013-16



Part number
1057

UPC: 729295236726

Also available for this application:

3-1058S	Timing Set
3-1058SX	Timing Set (no sprockets)
1058	Timing Chain
BG5089	Timing Chain Guide
BG5094	Timing Chain Guide
BT5122	Timing Chain Tensioner
BT5123	Timing Chain Tensioner
JB-7530	Lifter
JB-7531	Lifter

**** Always consult catalog listings for detailed application information****

MEMBER
A.E.R.A
P.E.R.A

“Quality in all we do.”

Melling Engine Parts • P.O. Box 1188 • Jackson, MI 49204
517-787-8172 • Fax 517-787-5304 • www.melling.com

MEMBER
A.C.A.
M.E.M.A