


**NOW  
AVAILABLE!**



**ANNOUNCES**

**NEW INTAKE VALVE FOR  
GM 3.5L & 3.9L ENGINES**

<b>BUICK</b>	<b>3.9 (237)</b>	<b>2009-11</b>	<b>Lucerne</b>	<b>CHEVY</b>	<b>3.9 (237)</b>	<b>2006-08</b>	<b>Uplander</b>
<b>BUICK</b>	<b>3.9 (237)</b>	<b>2006-07</b>	<b>Terraza</b>	<b>PONTIAC</b>	<b>3.5 (213)</b>	<b>2007-10</b>	<b>G6</b>
<b>CHEVY</b>	<b>3.5 (213)</b>	<b>2006-11</b>	<b>Impala</b>	<b>PONTIAC</b>	<b>3.9 (237)</b>	<b>2006-09</b>	<b>G6</b>
<b>CHEVY</b>	<b>3.9 (237)</b>	<b>2006-11</b>	<b>Impala</b>	<b>PONTIAC</b>	<b>3.9 (237)</b>	<b>2006</b>	<b>Montana</b>
<b>CHEVY</b>	<b>3.5 (213)</b>	<b>2007-10</b>	<b>Malibu</b>	<b>SATURN</b>	<b>3.5 (213)</b>	<b>2007-08</b>	<b>Aura</b>
<b>CHEVY</b>	<b>3.9 (237)</b>	<b>2006-07</b>	<b>Malibu</b>	<b>SATURN</b>	<b>3.9 (237)</b>	<b>2006-07</b>	<b>Relay</b>
<b>CHEVY</b>	<b>3.5 (213)</b>	<b>2006-07</b>	<b>Monte Carlo</b>	<b>SATURN</b>	<b>3.5 (213)</b>	<b>2008-10</b>	<b>Vue</b>

**Part number**

**V3043**

**Jobber Net**

**\$4.77**

**UPC: 729295192183**

Quantity required per engine (6)



**\*\* Always consult catalog listings for detailed application information\*\***

**MEMBER**  
**A.E.R.A**  
**P.E.R.A**

**“Quality in all we do.”**

Melling Engine Parts • P.O. Box 1188 • Jackson, MI 49204  
517-787-8172 • Fax 517-787-5304 • [www.melling.com](http://www.melling.com)

**MEMBER**  
**A.C.A**  
**M.E.M.A**