


**NOW
AVAILABLE!**



ANNOUNCES

**NEW OIL PUMP REPAIR KIT FOR
LEXUS/TOYOTA 5.7L ENGINES**

LEXUS	5.7 (345) DOHC (3UR-FE)	2008-19	LX570
TOYOTA	5.7 (345) DOHC (3UR-FE)	2008-19	Land Cruiser
TOYOTA	5.7 (345) DOHC (3UR-FE)	2008-19	Sequoia
TOYOTA	5.7 (345) DOHC (3UR-FBE)	2009-18	Sequoia
TOYOTA	5.7 (345) DOHC (3UR-FE)	2007-19	Tundra
TOYOTA	5.7 (345) DOHC (3UR-FBE)	2008-19	Tundra



**Part number
K544**

UPC: 729295105510

**** Always consult catalog listings for detailed application information****

“Quality in all we do.”

Melling Engine Parts • P.O. Box 1188 • Jackson, MI 49204
517-787-8172 • Fax 517-787-5304 • www.melling.com

MEMBER
A.E.R.A
P.E.R.A

MEMBER
A.C.A
M.E.M.A