


**NOW
AVAILABLE!**



ANNOUNCES

A NEW OIL PUMP REPAIR KIT

FORD 6.0L POWER-STROKE ENGINES

FORD	6.0-P (363)	OHV	2004-05	E350 Club Wagon
FORD	6.0-P (363)	OHV	2004-10	E350 Super Duty
FORD	6.0-P (363)	OHV	2004-10	E450 Super Duty
FORD	6.0-P (363)	OHV	2003-05	Excursion
FORD	6.0-P (363)	OHV	2003-07	F250 Super Duty
FORD	6.0-P (363)	OHV	2003-07	F350 Super Duty
FORD	6.0-P (363)	OHV	2003-07	F450 Super Duty
FORD	6.0-P (363)	OHV	2003-07	F550 Super Duty

Part number

K560

UPC: 729295105817



- Standard volume oil pump repair kit
- Does not include timing cover

**** Always consult catalog listings for detailed application information****

Melling Engine Parts

P.O. Box 1188 • Jackson, MI 49204 • www.melling.com