


**NOW
AVAILABLE!**



NEW CAMSHAFT ACTUATOR FOR GM 2.0L & 2.4L ECOTEC ENGINES

BUICK	2.0-V	(122)	2011-13	Regal	Pontiac	2.0-X	(122)	2007-09	Solstice
BUICK	2.0-V	(122)	2013-16	Verano	Pontiac	2.4-B	(145)	2007-08	G5
BUICK	2.4-C	(145)	2010	LaCrosse	Pontiac	2.4-B,0	(145)	2006-10	G6
CHEVROLET	2.0-X	(122)	2008-10	Cobalt	Pontiac	2.4-B	(145)	2006-09	Solstice
CHEVROLET	2.0-X,M	(122)	2008-10	HHR	Saab	2.0	(122)	2011	9-5
CHEVROLET	2.4-B	(145)	2006-08	Cobalt	Saturn	2.0-X	(122)	2007-10	Sky
CHEVROLET	2.4-W	(145)	2010	Equinox	Saturn	2.4-5,B	(145)	2007-09	Aura
CHEVROLET	2.4-P,V,U	(145)	2006-11	HHR	Saturn	2.4-B	(145)	2006-07	Ion
CHEVROLET	2.4-0,1,5,B,U,Z	(145)	2008-12	Malibu	Saturn	2.4-B	(145)	2007-10	Sky
GMC	2.4-W	(145)	2010	Terrain	Saturn	2.4-P,Z,1	(145)	2008-10	Vue



SERVICE GRADE COMPONENT

**Part number
VCTA-1008H
UPC: 729295237167**

**** Always consult catalog listings for detailed application information****

MELL-GEAR
Quality Melling Timing Parts Since 1946

Melling Engine Parts • P.O. Box 1188 • Jackson, MI 49204 • www.melling.com