

**NOW  
AVAILABLE!**



**ANNOUNCES**

# A NEW TIMING CHAIN GUIDE FOR GM 2.8L & 3.6L DOHC ENGINES

<b>BUICK</b>	<b>3.6-7</b>	<b>(217)</b>	<b>DOHC</b>	<b>2005-06</b>	<b>LaCrosse</b>
<b>BUICK</b>	<b>3.6-7</b>	<b>(217)</b>	<b>DOHC</b>	<b>2004-05</b>	<b>Rendezvous</b>
<b>CADILLAC</b>	<b>2.8-T</b>	<b>(170)</b>	<b>DOHC</b>	<b>2005-07</b>	<b>CTS</b>
<b>CADILLAC</b>	<b>3.6-7</b>	<b>(217)</b>	<b>DOHC</b>	<b>2004-05</b>	<b>CTS</b>
<b>CADILLAC</b>	<b>3.6-7</b>	<b>(217)</b>	<b>DOHC</b>	<b>2004-06</b>	<b>SRX</b>
<b>CADILLAC</b>	<b>3.6-7</b>	<b>(217)</b>	<b>DOHC</b>	<b>2005-07</b>	<b>STS</b>

1st design with roller secondary timing chain  
Replaces part stamped 12589010  
(Secondary guide Left - Upper)



Qty per application: 1

**Part number**

**BG7036**

**UPC: 729295316947**

This part number is also available in the 3-1007S timing set

**MELL-GEAR**  
Quality Melling Timing Parts Since 1946

Melling Engine Parts • P.O. Box 1188 • Jackson, MI 49204 • [www.melling.com](http://www.melling.com)