


**NOW
AVAILABLE!**



ANNOUNCES

A NEW AFM DELETE CAMSHAFT CHEVROLET/GMC 5.3L OHV ENGINES

CHEVROLET 5.3-C (325)	2014-19	Silverado 1500	GMC 5.3-C (325)	2014-19	Sierra 1500
CHEVROLET 5.3-F (325)	2019-20	Silverado 1500	GMC 5.3-F (325)	2019-20	Sierra 1500
CHEVROLET 5.3-R (325)	2016-18	Silverado 1500	GMC 5.3-R (325)	2016-18	Sierra 1500
CHEVROLET 5.3-C (325)	2015-20	Suburban	GMC 5.3-C (325)	2015-20	Yukon
CHEVROLET 5.3-C (325)	2015-20	Tahoe	GMC 5.3-C (325)	2015-19	Yukon XL

Part number

MC1429

UPC: 729295141877



- Eliminates the “AFM capability
- Requires non-AFM lifters and lifter guides
- AFM must be deleted both mechanically and electronically
- Module programming is required

**** Always consult catalog listings for detailed application information****

Melling Engine Parts

P.O. Box 1188 • Jackson, MI 49204 • www.melling.com