

**NOW AVAILABLE!**



**ANNOUNCES**

**NEW MDS DELETE KIT FOR**

# GM 5.3L LC9, LH6, LMG & LY5 ENGINES

|                  |                      |              |            |                |                       |
|------------------|----------------------|--------------|------------|----------------|-----------------------|
| <b>CHEVROLET</b> | <b>5.3-J,0,3,7</b>   | <b>(325)</b> | <b>OHV</b> | <b>2007-13</b> | <b>Avalanche</b>      |
| <b>CHEVROLET</b> | <b>5.3-J,M,3,0,7</b> | <b>(325)</b> | <b>OHV</b> | <b>2007-13</b> | <b>Silverado 1500</b> |
| <b>CHEVROLET</b> | <b>5.3-J,0,3,7</b>   | <b>(325)</b> | <b>OHV</b> | <b>2007-14</b> | <b>Suburban 1500</b>  |
| <b>CHEVROLET</b> | <b>5.3-J,0,3</b>     | <b>(325)</b> | <b>OHV</b> | <b>2007-14</b> | <b>Tahoe</b>          |
| <b>GMC</b>       | <b>5.3-J,M,3,0,7</b> | <b>(325)</b> | <b>OHV</b> | <b>2007-13</b> | <b>Sierra 1500</b>    |
| <b>GMC</b>       | <b>5.3-J,0,3</b>     | <b>(325)</b> | <b>OHV</b> | <b>2007-14</b> | <b>Yukon</b>          |
| <b>GMC</b>       | <b>5.3-J,0,3,7</b>   | <b>(325)</b> | <b>OHV</b> | <b>2007-14</b> | <b>Yukon XL 1500</b>  |

**Important MDS Delete Kit Notes**

- When installing a delete cam, the Active Fuel Management lifters must be replaced using Non-Active Fuel Management lifters.
- The valve lifter guides used in Non-Active Fuel Management engines are different from those used in Active Fuel Management Engines and must be replaced when installing the Non-Active Fuel Management lifters
- The VLOM Must Be Replaced With A Non-Active Fuel Management Valley Cover.
- Pushrod length must be checked during installation to verify that the correct length pushrods are being used
- The vehicle engine control module/Power train control module must be reprogrammed to turn off the Active Fuel Management System in the operating software



**Components must be used together**

| Component #      | Description           | Qty            |
|------------------|-----------------------|----------------|
| <b>MC1390</b>    | Camshaft              | 1 Camshaft     |
| <b>JB-2079</b>   | Valve Lifter          | 16 Lifters     |
| <b>MLG100</b>    | Lifter Guide          | 4 Guides       |
| <b>MF127</b>     | Thrust Plate          | 1 Thrust Plate |
| <b>VCTO-1000</b> | VVT Oil Control Valve | 1 Valve        |

**Part number**

**MDK300**

**UPC: 729295151999**

**\*\* Always consult catalog listings for detailed application information\*\***

**Melling Engine Parts**

P.O. Box 1188 • Jackson, MI 49204 • [www.melling.com](http://www.melling.com)