

**NOW  
AVAILABLE!**



**ANNOUNCES**

**A NEW TIMING CHAIN FOR**

# **FORD / LINCOLN 2.0L & 2.3L DOHC ENGINES**

<b>FORD</b>	<b>2.0-9</b>	<b>(122)</b>	<b>DOHC</b>	<b>2021-22</b>	<b>Bronco Sport</b>	<b>FORD</b>	<b>2.3-H</b>	<b>(140)</b>	<b>DOHC</b>	<b>2020-22</b>	<b>Explorer</b>
<b>FORD</b>	<b>2.0-9</b>	<b>(122)</b>	<b>DOHC</b>	<b>2019-22</b>	<b>Edge</b>	<b>FORD</b>	<b>2.3-H</b>	<b>(140)</b>	<b>DOHC</b>	<b>2019-22</b>	<b>Ranger</b>
<b>FORD</b>	<b>2.0-9</b>	<b>(122)</b>	<b>DOHC</b>	<b>2020-22</b>	<b>Escape</b>	<b>LINCOLN</b>	<b>2.0-9</b>	<b>(122)</b>	<b>DOHC</b>	<b>2020-22</b>	<b>Corsair</b>
<b>FORD</b>	<b>2.0-9</b>	<b>(122)</b>	<b>DOHC</b>	<b>2022</b>	<b>Maverick</b>	<b>LINCOLN</b>	<b>2.0-9</b>	<b>(122)</b>	<b>DOHC</b>	<b>2019-22</b>	<b>Nautilus</b>
<b>FORD</b>	<b>2.3-H</b>	<b>(140)</b>	<b>DOHC</b>	<b>2021-22</b>	<b>Bronco</b>	<b>LINCOLN</b>	<b>2.3-H</b>	<b>(140)</b>	<b>DOHC</b>	<b>2020-21</b>	<b>Corsair</b>



1078 is also available in timing kit 3-1078S

Qty Required: 1

**Part number**

**1078**

**UPC: 729295237310**

