


**NOW
AVAILABLE!**



ANNOUNCES

A NEW TIMING CHAIN TENSIONER ARM

FORD / LINCOLN 3.5L DOHC ENGINES

FORD	3.5-T	(213)	DOHC (Turbo)	2018-21	Expedition
FORD	3.5-G,4	(213)	DOHC (Turbo)	2017-20	F150
LINCOLN	3.5-T	(213)	DOHC (Turbo)	2018-22	Navigator



Qty Required: 1 (Right Hand)

Part number

BT7056

UPC: 729295317289

BT7056 is also available in timing kits 3-1079S and 3-1079SX



Quality Melling Timing Parts Since 1946