

NOW AVAILABLE!



ANNOUNCES

NEW TIMING SET FOR

FORD/LINCOLN 3.5L DOHC ENGINES

FORD	3.5-T (213) DOHC	2018-21	Expedition	FORD	3.5-4 (213) DOHC	2019-22	F150
FORD	3.5-D (213) DOHC	2021-22	F150	FORD	3.5-8 (213) DOHC	2021-22	F150
FORD	3.5-G (213) DOHC	2017-22	F150	LINCOLN	3.5-T (213) DOHC	2018-22	Navigator



Part number

3-1079SX

UPC: 729295237341

PROFESSIONAL GRADE - PREMIUM QUALITY
DOES NOT INCLUDE SPROCKETS

	UPC
1079	729295237327
BG7041	729295317234
BG7042	729295317241
BT7053	729295317258

	UPC
BT7054	729295317265
BT7055	729295317272
BT7056	729295317289

KIT INCLUDES (2) TIMING CHAINS, (2) TIMING CHAIN GUIDES (2) TIMING CHAIN TENSIONERS,
(2) TIMING CHAIN TENSIONER ARMS

**** Always consult catalog listings for detailed application information****



Quality Melling Timing Parts Since 1946

Melling Engine Parts • P.O. Box 1188 • Jackson, MI 49204 • www.melling.com