

**NOW
AVAILABLE!**



ANNOUNCES

A NEW TIMING CHAIN TENSIONER

FORD / LINCOLN 3.5L DOHC ENGINES


FORD	3.5-T	(213)	DOHC (Turbo)	2018-21	Expedition
FORD	3.5-D	(213)	DOHC (Turbo)	2021-22	F150
FORD	3.5-G	(213)	DOHC (Turbo)	2017-22	F150
FORD	3.5-4	(213)	DOHC (Turbo)	2019-22	F150
FORD	3.5-8	(213)	DOHC (Turbo)	2021-22	F150
LINCOLN	3.5-T	(213)	DOHC (Turbo)	2018-22	Navigator

Qty Required: 1 (Left Hand)

Part number

BT7053

UPC: 729295317258



BT7053 is also available in timing kits 3-1079S and 3-1079SX

