


**NOW
AVAILABLE!**



ANNOUNCES

A NEW EXHAUST VALVE FOR GM 2.5L DOHC ENGINES

BUICK	2.5-A (153) DOHC	2017-20	Envision	CHEVROLET	2.5-A,L (153) DOHC	2014-19	Impala
BUICK	2.5-Z (150) DOHC	2018-19	LaCrosse	CHEVROLET	2.5-A,L (153) DOHC	2013-15	Malibu
CADILLAC	2.5-A (150) DOHC	2013-16	ATS	GMC	2.5-A (153) DOHC	2017-21	Acadia
CHEVROLET	2.5-A (153) DOHC	2019-21	Blazer	GMC	2.5-A (153) DOHC	2015-21	Canyon
CHEVROLET	2.5-A (153) DOHC	2015-21	Colorado				

EXHAUST VALVE /
8 required

Part number

V3442

UPC: 729295192534

Use with V3441 Intake Valve



**** Always consult catalog listings for detailed application information****

“Quality in all we do.”

Melling Engine Parts • P.O. Box 1188 • Jackson, MI 49204 • www.melling.com