

**NOW  
AVAILABLE!**



**ANNOUNCES**

# TIMING CHAIN SET WITH OIL PUMP GM 5.3L, 6.0L & 6.2L OHV ENGINES

BUICK	5.3	(325)	2008-09	LaCrosse	CHEVROLET	5.3	(325)	2007-08	Trailblazer
BUICK	5.3	(325)	2007	Rainier	CHEVROLET	6.0	(364)	2011-17	Caprice
CADILLAC	6.2	(376)	2009-14	CTS	CHEVROLET	6.2	(376)	2012-15	Camaro
CHEVROLET	5.3	(325)	2007-09	Avalanche	GMC	5.3	(325)	2007-09	Envoy
CHEVROLET	5.3	(325)	2009	Express 1500	GMC	5.3	(325)	2009	Savana 1500
CHEVROLET	5.3	(325)	2007-09	Impala	GMC	5.3	(325)	2007-09	Sierra 1500
CHEVROLET	5.3	(325)	2007	Monte Carlo	GMC	5.3	(325)	2009	Yukon
CHEVROLET	5.3	(325)	2007-09	Silverado 1500	GMC	5.3	(325)	2007-09	Yukon XL
CHEVROLET	5.3	(325)	2007-09	Suburban 1500	PONTIAC	5.3	(325)	2007-08	Grand Prix
CHEVROLET	5.3	(325)	2009	Tahoe	PONTIAC	6.0	(364)	2008-09	G8

**Part number  
TOPK-1003  
UPC: 729295285663**



**KIT INCLUDES:**  
M365 STANDARD VOLUME OIL PUMP  
(1) 3SRH60 TIMING CHAIN  
(1) S827 CRANKSHAFT SPROCKET  
(1) S894 CAMSHAFT SPROCKET  
(1) BT5490 TIMING CHAIN TENSIONER

**\*\* Always consult catalog listings for detailed application information\*\***

**MELL-GEAR**  
Quality Melling Timing Parts Since 1946

Melling Engine Parts • P.O. Box 1188 • Jackson, MI 49204 • [www.melling.com](http://www.melling.com)