

**NOW  
AVAILABLE!**



**NEW TIMING CHAIN TENSIONER ARM**

**LEXUS/TOYOTA 4.6L & 5.0L DOHC ENGINES**

**(Includes Engine Codes 1UR-FSE, 1UR-FE, 2UR-FSE & 2UR-GSE)**

<b>LEXUS 4.6 (4608cc) DOHC 2008-11 GS460</b>	<b>LEXUS 5.0 (4968cc) DOHC 2018-22 LC500</b>
<b>LEXUS 4.6 (4608cc) DOHC 2010-22 GX460</b>	<b>LEXUS 5.0 (4968cc) DOHC 2008-16 LS600h</b>
<b>LEXUS 4.6 (4608cc) DOHC 2007-17 LS460</b>	<b>LEXUS 5.0 (4968cc) DOHC 2015-22 RC F</b>
<b>LEXUS 5.0 (4968cc) DOHC 2016-20 GS F</b>	<b>TOYOTA 4.6 (4608cc) DOHC 2010-12 Sequoia</b>
<b>LEXUS 5.0 (4968cc) DOHC 2008-14 IS F</b>	<b>TOYOTA 4.6 (4608cc) DOHC 2010-19 Tundra</b>



Right Hand - Qty 1 required

**Part number**

**BT7060**

**UPC: 729295317487**

**\*\* Always consult catalog listings for detailed application information\*\***