


**NOW  
AVAILABLE!**



**MELLING™**  
**TIMING COMPONENTS**

**ANNOUNCES**

**NEW CAMSHAFT ACTUATOR FOR**

# **GM 2.8L, 3.0L, 3.2L & 3.6L ENGINES**

<b>BUICK</b>	<b>3.0 (182) DOHC</b>	<b>2010</b>	<b>GMC</b>	<b>3.0 (182)</b>	<b>DOHC</b>	<b>2010-12</b>
<b>BUICK</b>	<b>3.6 (217) DOHC</b>	<b>2007-21</b>	<b>GMC</b>	<b>3.6 (217)</b>	<b>DOHC</b>	<b>2007-17</b>
<b>CADILLAC</b>	<b>2.8 (170) DOHC</b>	<b>2007, 2010-11</b>	<b>PONTIAC</b>	<b>3.6 (217)</b>	<b>DOHC</b>	<b>2007-09</b>
<b>CADILLAC</b>	<b>3.0 (182) DOHC</b>	<b>2010-14</b>	<b>SAAB</b>	<b>2.8 (170)</b>	<b>DOHC</b>	<b>2011</b>
<b>CADILLAC</b>	<b>3.6 (217) DOHC</b>	<b>2007-19</b>	<b>SATURN</b>	<b>3.6 (217)</b>	<b>DOHC</b>	<b>2007-10</b>
<b>CHEVROLET</b>	<b>3.0 (182) DOHC</b>	<b>2010-12</b>	<b>SUZUKI</b>	<b>3.2 (3195cc)</b>	<b>DOHC</b>	<b>2009-10</b>
<b>CHEVROLET</b>	<b>3.6 (217) DOHC</b>	<b>2008-21</b>	<b>SUZUKI</b>	<b>3.6 (3564cc)</b>	<b>DOHC</b>	<b>2008-09</b>

Qty 1 Required  
Right Hand - Intake

**Part number**

**VCTA-1011H**

**UPC: 729295285908**



SERVICE GRADE COMPONENT

**\*\* Always consult catalog listings for detailed application information\*\***