


**NOW
AVAILABLE!**



MELLING™
TIMING COMPONENTS

ANNOUNCES

NEW CAMSHAFT ACTUATOR FOR

GM 2.8L, 3.0L, 3.2L & 3.6L ENGINES

BUICK	3.0 (182) DOHC	2010	GMC	3.0 (182)	DOHC	2010-12
BUICK	3.6 (217) DOHC	2007-21	GMC	3.6 (217)	DOHC	2007-17
CADILLAC	2.8 (170) DOHC	2007, 2010-11	PONTIAC	3.6 (217)	DOHC	2007-09
CADILLAC	3.0 (182) DOHC	2010-14	SAAB	2.8 (170)	DOHC	2011
CADILLAC	3.6 (217) DOHC	2007-19	SATURN	3.6 (217)	DOHC	2007-10
CHEVROLET	3.0 (182) DOHC	2010-12	SUZUKI	3.2 (3195cc)	DOHC	2009-10
CHEVROLET	3.6 (217) DOHC	2008-21	SUZUKI	3.6 (3564cc)	DOHC	2008-09

Qty 1 Required
Left Hand - Intake

Part number

VCTA-1012H

UPC: 729295285915



SERVICE GRADE COMPONENT

**** Always consult catalog listings for detailed application information****