

**NOW
AVAILABLE!**



ANNOUNCES

NEW TIMING SET FOR

FORD / LINCOLN 3.5L DOHC ENGINES

FORD	3.5-T (213) DOHC	2015-17 Expedition
FORD	3.5-T (213) DOHC	2011-14 F150
FORD	3.5-G (213) DOHC	2015-16 F150
LINCOLN	3.5-T (213) DOHC	2015-17 Navigator



Part number

3-1049SW

UPC: 729295286448

PROFESSIONAL GRADE, PREMIUM QUALITY
DOES NOT INCLUDE CAMSHAFT VVT SPROCKETS

INCLUDES IDLER SPROCKET WITH WATER PUMP COVER & GASKET

KIT INCLUDES (1) 1049 TIMING CHAIN, (2) 1050 TIMING CHAINS, (2) BG7008 TIMING CHAIN GUIDES, (1) BG7009 TIMING CHAIN GUIDE, (1) BG7010 TIMING CHAIN GUIDE, (1) BG7011 TIMING CHAIN GUIDE, (1) BT7007 TIMING CHAIN TENSIONER, (2) BT7008 TIMING CHAIN TENSIONERS (1) BT7009 TIMING CHAIN TENSIONER, (1) S1239 CRANKSHAFT SPROCKET, (1) S1326WC IDLER SPROCKET W/ WATER PUMP COVER

**** Always consult catalog listings for detailed application information****

Melling Engine Parts • P.O. Box 1188 • Jackson, MI 49204 • www.melling.com