

**NOW
AVAILABLE!**



ANNOUNCES

**NEW CAMSHAFT ACTUATOR FOR
GM 5.3L & 6.2L ENGINES**

CHEVROLET	6.2	VIN J	2015-20	Escalade
CHEVROLET	6.2	VIN 7	2016-21	Camaro
CHEVROLET	6.2	VIN 7	2014-19	Corvette
CHEVROLET	5.3	VIN C,R	2014-19	Silverado 1500
CHEVROLET	6.2	VIN J	2014-18	Silverado 1500
CHEVROLET	5.3	VIN C	2015-20	Suburban
CHEVROLET	6.2	VIN J	2019-20	Suburban
CHEVROLET	5.3	VIN C	2015-20	Tahoe
CHEVROLET	6.2	VIN J	2018-20	Tahoe
GMC	5.3	VIN C,R	2014-19	Sierra 1500
GMC	6.2	VIN J	2014-18	Sierra 1500
GMC	5.3	VIN C,	2015-20	Yukon
GMC	6.2	VIN J	2015-20	Yukon

Qty 1 Required

**Part number
VCTA-1015H
UPC: 729295286561**



VVT Oil Control Valve Can Not Be Reused And Must Be Replaced Upon Re-Assembly
Order VCTO-1001 Oil Control Valve Separately As Needed
SERVICE GRADE COMPONENT

**** Always consult catalog listings for detailed application information****